



Status of the GPS-Trigger Board V.2

A. Corvaglia


10/05/2017



Outlook




- VME GPS/Trigger board debugging status
 - Timing
 - Position
- Trigger and GPS functionality implemented
- Debugging plan









Time

- A shift of one second was found between PPS signal and the correlated data information. This error was fixed by a reconstruction of the calendar implemented into the FPGA
- The choice between UTC time and GPS time is now implemented into GPS engine board (we use the UTC time for EEE)


Position

 For default the engine GPS freeze the surveyed position information (latitude/longitude) to the average value after 2k acquisition from the first start. This procedure allow a better accuracy on the time data. We decided to maintain this working condition.

10/05/2017







Trigger + clock distribution

Now the trigger section can work even without the engine GPS module (in this condition the time accuracy is limited on the precision of the oscillator on the board)

GPS Setup

- For default, the setup of the engine GPS board should made through a dedicated external board. This procedure complicates the installation and the replacement of the engine GPS
- Now the setup of the engine GPS board in made by the FPGA on the same VME board. A code implemented on the FPGA (now under test) configures and saves the data on the flash memory of the engine GPS.

10/05/2017



Summay



- Avallabile:
 - 7 VME GPS/trigger boards
 - 4 engine GPS boards
- 5 trigger boards (no GPS functionality implemented yet) will be available for the end of next week (please let me know the addresses to send them)
 - Next we will need to get back them to install the GPS firmware on the FPGA
- GPS firmware debugging is estimate in about 2 weeks

